

# Stoner

## ***PolyOff™ B510***

### **TIME SAVING MOLD AND TOOL CLEANER**

POWERFUL FORMULA cleans molds and tools quick and EASY. Completely removes cured polyurethane, mold release and other build-up from tooling, molds, and machinery. Use only on steel, aluminum and other metal tooling. Before using, always test for compatibility

**DIRECTIONS:** Read entire label before using. Wear butyl rubber gloves and safety goggles to protect skin and eyes. Saturate the mold build-up with B510 and allow to soak. Soaking time may vary depending on degree and type of build-up as well as temperature of mold. Allow B510 to soak in until build-up easily wipes away with a rag or soft parts cleaning brush. Difficult areas may require second application, 24 hours of soaking, or scrubbing with soft cleaning brush or rag. Remove excess cleaner with a rag or allow to air dry. B510 is a strong cleaner which may be harmful to certain plastics, paints, or other sensitive materials. Always test in a small area before using. Immediately after use, let B510 evaporate from cloths or other applicators in a well ventilated area, away from sources of ignition. Dispose of rags or applicators in a metal container in accordance with local, state, and federal regulations.

**DANGER:** FLAMMABLE Keep away from sunlight, heat, sparks, or open flame. Keep container cool and dry, and away from sources of ignition. Keep container tightly closed. EYE IRRITANT. Wear skin and eye protection. Avoid contact with eyes and prolonged or repeated contact with skin. HARMFUL OR FATAL IF SWALLOWED. Do not ingest. For industrial use only. Keep out of reach of children. Before using, for more specific health and safety information, always refer to the Material Safety Data Sheet for this product available from your employer or Stoner, Inc. Contains: NJ Trade Secret Registry #80100382-5054P; xylene, CAS# 1330-20-7; NJ Trade Secret Registry #80100382-5055P; petroleum distillates, CAS# 8052-41-3;

**FIRST AID** If overcome by vapors, remove person from contaminated area. Call physician immediately. For eye contact, flush thoroughly with water for 15 minutes. Call physician immediately. For skin contact, wash thoroughly with warm soapy water. Remove contaminated clothing immediately and wash before reuse. If swallowed, do not induce vomiting. Call physician immediately.

**FOR FIRE:** Extinguish with dry chemical, carbon dioxide, or foam.

**FOR SPILL:** Soak up with inert absorbent material. Collect and dispose of in accordance with local, state, and federal regulations.

**ADDITIONAL INFORMATION:** Store this product in a cool, dry, well-ventilated area. Emptied container retains vapor and product residue. Do not cut, drill, grind, or weld on or near this container. Do not reuse this container.